# **Maintenance and Operations Report**

### May 2021

### **THS**

Performed a low pressure pump test with the assistance of the Toledo Fire Department. The test was successful and verified proper hookup with the new building.

### **TMS**


The lights for the play shed are installed. These lights are on a 60 minute timer that will be active between 6am and 1100pm. This will make the play shed safer and brighter, and will make it more usable during the evenings and winter days. We also had Northfork Asphalt come out to seal the cracks and grooves in the play surface, and then our crew put a seal coat over the surface to protect it!





Lights

Cracks Repaired



**Seal Coat** 

#### TMS cont.

To free up room inside the building for storage needs we have procured a container with dual roll-up doors, it is scheduled to arrive on May 28th.

#### **TES**

Repaired boiler 3 as it was having lockout issues related to the condensate draining system.

Repaired the freezer – It had a bad contactor that was causing the defrost cycle to be skipped.

Removed stump from rear parking area.

### **Softball Complex**

Replaced old broken/outdated lighting in the Concession stand with LED fixtures, it's much brighter in there!



# **Disinfecting practices**

Our custodial team continues to do a great job at keeping all areas clean, disinfected and safe for our staff and students.

# <u>PPE</u>

Levels are an acceptable level for continued operation.

# **Maintenance Shop**

Replaced non-operational heater unit.

Added foam board insulation to rafters and roll-up doors to help keep building at temperature and to lessen heating costs.